

Stormwater Management Basin Inspection Report

<u>Basin Number</u>	5024	<u>COUNTY</u>	5
<u>Inspector</u>	D.W.HARVEY	<u>Inspection Date</u>	February 23, 2009
<u>SWB TYPE</u>	DETENTION		
<u>Overall Rating</u>	A	<u>Maintenance Priority Rating</u>	A

Inspection Results

Feature

<u>Watershed Condition</u>	1		
<u>Q-in (Discharge Points) Condition</u>	1	<u>Q-in Stability</u>	1
<u>Fence Condition</u>	NO		
<u>Access Condition</u>	1		
<u>Vegetation Condition</u>	1		
<u>Contamination</u>	2		
<u>Debris</u>	1		
<u>Ponding</u>	0		
<u>Forebay</u>	0		
<u>Upstream Embankment Cover</u>	1	<u>Upstream Embankment Stability</u>	2
<u>Downstream Embankment Cover</u>	1	<u>Downstream Embankment Stability</u>	1
<u>Downstream Seep</u>	1		
<u>Emergency Earthen/Vegetated Spillway Stability</u>	1	<u>Emergency Earthen/Vegetated Spillway Opening</u>	1
<u>Riser Low-Flow Orifice</u>	1	<u>Riser Low-Flow Trashrack</u>	1
<u>Riser Upper-Stage Orifice</u>	0	<u>Riser Upper-Stage Trashrack</u>	1
<u>Riser Top - Overflow Spillway</u>	1	<u>Riser Trashrack</u>	1
<u>Riser Sediment</u>	1	<u>Riser Structure</u>	1
<u>Principal Spillway Barrel</u>	1	<u>Spillway Outfall Protection</u>	1